

To: LaPoma, Jennifer[LaPoma.Jennifer@epa.gov]; Frank Tsang[TsangC@cdmsmith.com];
KirchnerSF[KirchnerSF@cdmsmith.com]; Ben Hammond[hammondbh@cdmsmith.com]
Cc: John Rolfe[jrolfe@demaximis.com]; Amy Picunas[PicunasAE@cdmsmith.com]; Meredith
Passaro[PassaroML@cdmsmith.com]; Vaughn, Stephanie[Vaughn.Stephanie@epa.gov]; Basso,
Ray[Basso.Ray@epa.gov]
From: Hoppe, Michael
Sent: Thur 5/29/2014 8:27:38 PM
Subject: Inspection of Cap

All,

The exposed sand/habitat layer looks to be adequate. I spoke to Roy, Ben and Rachel at the Site and passed the word here.

Please note that areas in the northern most cap area are not visible for inspection, even at low tide.

The boat launch area was capped with some of the extra sand and exposed pieces of fabric were covered with anchor stone on the near shore areas. The areas in the park impacted by GLDD have been raked and seeded. These should be re-inspected in a couple of weeks to ensure adequate growth in the bare spots is achieved.

The crew can demobilize equipment.

Please contact me with any questions or concerns.

This day has been a long time coming. Thank you all for your efforts!

Michael Hoppey